

Red Hill Tank Inspection and Record of Maintenance Intervals

Tank	Status	Fuel Type	Last Inspection or Record of Maintenance	Approximate last inspection of any kind (as of 2016)	Next Inspection Scheduled in Report	Approximate years between last & scheduled inspection
1	Out of service	N/A	2007	9	N/A	N/A
2	Active	JP8	2008	8	2028	20
3	Active	JP8	1982	34	2012	30 ?
4	Active	JP8	1982	34	2011	29 ?
5	Active	JP8	2014	2	2009	-5
6	Active	JP8	2007	9	2027	20
7	Active	JP5	1998	18	2014	16 ?
8	Active	JP5	1998	18	2014	16 ?
9	Active	JP5	1996	20	2012	16 ?
10	Active	JP5	1998	18	2015	17 ?
11	Active	JP5	1980	36	2011	31 ?
12	Active	JP5	1995	21	2012	17 ?
13	Active	F76	1995	21	2013	18 ?
14	Active	F76	1995	21	2010	15 ?
15	Active	F76	2005	11	2026	21
16	Active	F76	2006	10	2026	20
17	Active	JP5	2012	4	2009	-3
18	Active	JP5	1963	53	2010	47 ?
19	Out of service	N/A	1989	27	N/A	N/A
20	Active	JP5	2008	8	2028	20